

## ARRA FHWA Award 0023071

Award Date: 3/3/2009 Click for 1512 Report

ARRA Type: MDOT Project Status: Completed 50% or more

Project Name: US 45 FR KEMPER CL TO BROOKSVILLE

Award Description: Highway Infrastructure Investment Grants

Project Description: This project will resurface and extend the life of the pavement on US 45 from the Kemper

County Line to Brooksville in Noxubee county.

Infrastructure Rationale: 4R Resurfacing. Preserve/Create jobs; and economic recovery. Invest in

transportation.

Award Amount: \$11,987,698.00

Jobs Creation To Date: 72.76

Total Federal ARRA Received: \$11,987,698.00

Location: Macon 39341

Total Federal ARRA Expenditure: \$11,987,697.00

**VENDOR PAYMENTS** 

Vendor Name: { name not entered }

DUNS: **610327744** Payment: **\$11,559,831.00** 

Service Description: Overlaying US 45 from the Kemper County Line to Brooksville

**MDOT PROJECTS** 

Project Number: 105246-301000 Responsible Agency: MDOT

Location: District 5, Noxubee County Route: 45

Plan Begin: 3/4/2009 Total Estimated Cost: \$12,019,164.88

Plan End: 7/6/2010 Project Let: 3/24/2009 Total Expended: \$12,019,164.88

Termini: \*\*US 45 FR KEMPER CL TO BROOKSVILLE (OVERLAY) (MAS 4563, 4562, 1770, 4568 thru

4570 NB)



## ARRA FHWA Award 0023071

## **PROJECT** MAP

ig Springs

tile server took longer than 10000 milliseconds than 10000 milliseconds than 10000 milliseconds to respond.

Tile server timeout: The Tile server timeout: The tile server took longer to respond.

The server timeout: The Tile server timeout: The tile server took longer to respond.

tile server took longer than 10000 milliseconds to respond.

Tile server t tile server than 10000 to res

tile server took longer than 10000 milliseconds than 10000 milliseconds to respond.

Tile server timeout: The Tile server timeout: The tile server took longer to respond.

Tile server timeout: The Tile server timeout: The tile server took longer to respond.

tile server took longer than 10000 milliseconds than 10000 milliseconds than 10000 to respond.

Tile server t tile server to res

Tile server timeout: The tile server took longer to respond.

Tile server timeout: The tile server took longer than 10000 milliseconds than 10000 milliseconds to respond.

tile server took longer to respond.

Tile server timeout: The Tile server timeout: The tile server took longer than 10000 milliseconds than 10000 milliseconds to respond.

Tile server t tile server than 10000 to res

5 km 3 mi

© AND, © 2014 Microsoft Corporation